ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0121, W0113, W0111, W0117, W0084, W0088, W0129	NA, 3rd Crs	Jakkur Layout Ayyappa Temple
Segment No.	**Total Length (m)**	
7/S-W0121/S125653	441.16	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	163.53	77.598373	13.071877	77.598001	13.070445	Ayyappa Temple Road	Talakavery Layout
2	80.78	77.597919	13.072695	77.597773	13.071994	13th Cross Road	Dead End
3	67.38	77.597584	13.072725	77.597458	13.072129	14th Cross Road	Dead End
4	129.47	77.596940	13.072775	77.596669	13.071637	Main Road	Dead End

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to drains of roads next to Ayyappa Temple of Jakkur layout and Improvements to drains of roads of Jakkur layout in ward No.07 Byataraya	7000000	2018-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender	1. Construction Of RCC Drains.2.Providing And laying RCC Covering Slabs.	007-18-000097
Work Order No.	**Work Order Date**	**Period of Extention**
EE(Project)/Ynk Zone/WO/24/2019-20	27/05/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
27/09/2019	26/09/2021	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

Ramesh U		0.00
Phone No.	**E-Mail ID**	
7846844447		

Field Inspection Details

Number of Trees	**Any Other Information**	**Name**
0		Pushpalatha.N.D
Date of Inspection	**Remarks**	
27/09/2019		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0121, W0113, W0111, W0117,

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	R L.Parameshwaraiah	10/10/2019	27/10/2019	As proposed
SE	Vijay Kumar	05/10/2019	27/10/2019	Forwarded
EE	Yarappareddy H.V	01/10/2019	27/10/2019	approved
AEE	Chidanand K.R	01/10/2019	27/10/2019	verified
AE	Pushpalatha N D	01/10/2019	27/10/2019	Mobile Verification Done
AE	Pushpalatha N D	27/09/2019	27/10/2019	Forwarded

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0121, W0113, W0111, W0117,